

# Work Order ID 93950

December-07-12 2:23:15 PM

\*93950\*

Page 1

Item ID: D350-607-511 Accept \*N900040100\* Setup Start \*NS1\*  
Revision ID: Stop \*NS2\*  
Item Name: Quick Release Basket Mounting Installation  
Start Date: 11/27/12 Start Qty: 1.00 \*1\* Cust Item ID:  
Required Date: 11/28/12 Req'd Qty: 1.00 \*1\* Customer: CU-DAR001  
Reference: RMA RA111449 - RETURN  
Approvals: Process Plan: ✓ Date: Tooling: Date: Run Start \*NR1\*  
QC: SPC (Y/N): Date: Stop \*NR2\*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D350-607-3	A

100 SL 0.00  
\*100\*  
QC Memo 0.00  
Quality Control INSPECT RA111449  
1 X D350-607-511 B87122 CHG002 (DAS 16) 12/11/12 (SL)

110 Identify as per dwg & Stock Location: PKG 012 0.00  
\*110\*  
Packaging SL 12/12/11 Memo 0.00  
Packaging REPACKAGE PER PPP USING NEW B/N  
NEW LABELS AND PAPERWORK REQ'D @ CHG002 12/12/11 12-12-10 (DAS 20 9-89)

120 QC21- Final Inspection - Work Order Release 0.00  
\*120\*  
QC Memo 0.00  
Quality Control 12/12/11 ME 12-12-11

1000

1000

# **RA111449 D350-607-511**

## **B87122**

Received @ Dart November 23<sup>rd</sup>, 2012  
Inspected @ Dart November 26<sup>th</sup>, 2012

Customer: HELISTREM INC  
Customer Contact: MARK PISKURA  
Shipped from: COSTA MESA CA, USA

### **Instructions for RA 111449 D350-607-511 B87122 CHG002**

- Kit is complete
- Needs new paper work and labels
- Needs new BATCH # to go back into stock
- Needs new work order

**Time Estimate** = 1 HOUR ONLY (stores)

**Departments Required:** Stores (restocking)

**Pictures Attached** = NO

**QTY INSPECTED** = x1

**THIS INSTRUCTION SHEET MUST  
BE ATTACHED TO THE  
RESTOCKING WORK ORDER AT  
ALL TIMES!!!!**

